

STREET	TYPE	RATING	WARD	CRACK SEAL	SEAL COAT	RECONST. YEAR	RESURF. YEAR	Minor Repairs	COMMENTS	CWD Recommendation	Flood Control Project Area	DEO Identified Priority
ARGONNE (Adrian TO ARDMORE)	A/C	1	2	94, 96							Yes	
BRIDGEVIEW	A/C	1	1	95	97				T.C.R.			
BRYAN	A/C	1	1	93,96,00	93,96,00							
CAMPUS	A/C	1	4	94, 97	97							
COLLEGE	A/C	1	4	94								
<b>DARTFORD</b>	A/C	1	1	95	97				Partial Curb Repairs	Replace		
<b>DIVISION</b>	A/C	1	3	95, 01	97				Curb Replacement			
FAY	A/C	1	1	93,00	93,96,00							
LAUREL	A/C	1	2	94, 99	97							
MAPLEGROVE	A/C	1	3	95					T.C.R.	Replace	Yes	
MIRAMAR (BEXLEY TO VERONA)	A/C	1	3/4	95	97				T.C.R., C.S.		Yes	
<b>ROANOKE</b>	A/C	1	1	95					T.C.R.			
ROBERTS	A/C	1	1	95	97				T.C.R.			
<b>SHEFFIELD (MAYFIELD TO BELVOIR)</b>	A/C	1	3	93,00	93, 95, 99				T.C.R. 1612-MAYFIELD			
BEACONWOOD	A/C	2	3		95, 99							
COLONY (MIRAMAR TO WRENFORD)	AC	2	4	94, 96	99				T.C.R.			
E. BERWALD	A/C	2	2	94, 96	97				T.C.R., Pot hole repairs	Replace		
<b>EASTWAY (MIRMAR TO WRENFORD)</b>	A/C	2	4	94,96,00	96,00							
EASTWAY (WARRENSVILLE TO MIRIMAR)	A/C	2	4	94,96,00	96,00							
EASTWAY (WEST OF WARRENSVILLE)	A/C	2	4	94, 96	96				S.C.	Replace		
EMERSON	A/C	2	2	94, 96	97				T.C.R., C.S.			
<b>GOLFWAY</b>	A/C	2	3	93, 97	93, 97							
HAYWOOD	A/C	2	1	94, 96	93, 95, 98			2007	ht Repair by SE Service			
HOMESTEAD (ADRIAN TO ELMWOOD)	C	2	2	93, 95, 98					Joint Repair			
HOMESTEAD (W. ANDERSON TO ADRIAN)	A/C	2	1	95					T.C.R.			
LOWDEN	A/C	2	1	95,01	97				C.S.			
MACKALL	A/C	2	4	93, 94, 97	93, 96				S.C.	Replace	Yes	
MONARCH (W. ANDERSON TO ADRIAN)	A/C	2	1	96	97							
<b>NEVILLE (BELVOIR TO GREEN)</b>	A/A	2	3	94, 99	93,95,00	82				Replace		
<b>SHERBROOK</b>	A/C	2	1	93, 96	93,96,01				C.S., S.C.			
SHERIDAN	A/C	2	3	94, 97	2004							
SHERWOOD	A/C	2	1	95					T.C.R.			
TEMBLEHURST	A/C	2	4	94	95, 99				T.C.R.			
WEST ANDERSON	A/C	2	1	93, 97	93, 97				T.C.R.			
ADRIAN (MONARCH TO GREEN)	C	3	2	93, 94, 96				2007	C.S.			
AZALEA	C	3	1	95					Joint repairs			

STREET	TYPE	RATING	WARD	CRACK SEAL	SEAL COAT	RECONST. YEAR	RESURF. YEAR	Minor Repairs	COMMENTS	CWD Recommendation	Flood Control Project Area	DEO Identified Priority
<b>BAYARD (BELVOIR TO GREEN)</b>	A/C	3	3	94,01	95,00				T.C.R.			
BERWICK LANE	C	3	2						C.S., Minor jnt. Repair			
BILTAMY	A/C	3	3	95,01	97							
BIRCHWOLD	A/C	3	4	94, 99	93,96,01					Replace		
CAPT. MONTAGANO	C	3	2	93, 99								
COLONY (WARRENSVILLE TO MIRAMAR)	A/C	3	4	94, 96	97				C.S.			
DEAN	C	3	3	95, 98					T.C.R.			
DELROY	A/A	3	2	95	93, 95, 99	82			C.S.			
EDENWOOD	C	3	2	94, 98	2004				T.C.R.			
ELMWOOD (CITY LIMIT TO WINSTON)	A/C	3	2	94, 99	97,00							
ELMWOOD (EAST OF BELVOIR)	A/C	3	2	94, 99	93,95,96,00							
FARNHURST (DORSH TO CITY LIMIT)	C	3	2	94, 99								
<b>FRANCIS COURT</b>	A/C	3	2	94, 99	93, 97							
FREEMONT	A/C	3	1	94, 99	93, 95, 99				Rejuvenation	Replace		
GENESEE	A/C	3	3	93, 99	93,96,01				S.C.			
GLENSIDE	A/C	3	1	95,01	97				C.S.			
GRANTLEIGH	A/C	3	2		2004				S.C.			
GREENVALE (PRINCETON TO RUPLE)	A/C	3	1	95	93, 97				C.S.			
GREENVALE (RUPLE TO GREEN)	A/C	3	1	95	93, 97	86			C.S.	Replace		
GREENWOLD	A/C	3	4	94, 98	93, 95, 98					Replace		
GROSVENOR (FENWICK TO WARRENSVILL)	A/C	3	4	97	96							
HARWOOD	A/C	3	3	93, 97	93, 97				C.S.			
HINSDALE	A/C	3	3	93, 99	93, 97				<b>C.S.</b>			
HOMESTEAD (ELMWOOD TO ARDMORE)	A/A	3	2	93, 95	93, 98	82			C.S.			
LACLEDE	A/C	3	3	94,96,01	95, 99				C.S.			
LANCASTER	A/A	3	1	95,01	95,99	85			C.S.			
MAYWOOD	A/C	3	3	94, 99	93, 95, 99				Needs Area Repairs		Yes	
<b>MCFARLAND, Harwood to K.George</b>	C	3	1	93, 99					C.S., Minor jnt. Repair			
MERRYMOUND	A/C	3	1	94, 99	93, 95, 99				Rejuvenation, C.S.	Replace		
MURRAY	A/C	3	1	95	97				C.S.			
OAKMOUNT	A/C	3	3	94, 99	93, 95, 99				C.S., Area Repairs		Yes	
PIERMONT (ADRIAN TO ELMWOOD)	A/A	3	2	94, 99	93, 95, 99	82						
PIERMONT (ROBERTS TO ADRIAN)	A/A	3	1	94, 97	93, 95, 98	82			C.S.			
RAINBOW (4550 TO OAKMOUNT)	A/A	3	3	95, 01	93, 97	82						
RAINBOW (GREEN TO 4550)	A/A	3	3	95, 01	93, 97							
RENWOOD	A/A	3	3	01	93, 97	82						

STREET	TYPE	RATING	WARD	CRACK SEAL	SEAL COAT	RECONST. YEAR	RESURF. YEAR	Minor Repairs	COMMENTS	CWD Recommendation	Flood Control Project Area	DEO Identified Priority
<b>RUPLE</b>	A/C	3	1	95				2007	ht Repair by SE Service			
RUSHTON (GREEN TO DEAN)	C	3	3	94, 98					T.C.R.			
RUSHTON (NEVILLE TO RENWOOD)	A/A	3	3	94, 99	93,95,01	82			S.C.			
SHIRLEY	A/C	3	3	95,01	97							
SOUTH LYN CIRCLE (SOUTH)	C	3	2									
STILMORE	A/C	3	4	94, 97	97				T.C.R., C.S.			
STUART	A/C	3	1	94, 99	93, 95, 99				C.S.			
TAMALGA	A/C	3	2	94, 96	96,00				CURBS REPAIRED 2003			
<b>VERONA (MIRAMARTO WRENFORD)</b>	A/C	3	4		00				Joint Repair, C.S.			
WEST CLAIRE	A/C	3	3	94, 99	97							
WESTDALE	A/C	3	3	94,96,01	95, 99				C.S.			
<b>WILBURN</b>	C	3	2	93, 96				2007	ht Repair by SE Service			
<b>WILBURN CIRCLE</b>	C	3	2					2007	ht Repair by SE Service			
WILMINGTON	A/C	3	4	97	93, 97				T.C.R., C.S.	Replace		
<b>WINSTON (ARDMORE TO GRANTLEIGH)</b>	A/C	3	2		93,96,01				S.C.		Yes	
ADRIAN (WINSTON TO BELVOIR)	A/A	4	2	94, 96	93, 97	82			C.S.			
AMMON	A/S	4	1		2004					Replace		
ANGELA	C	4	2	93, 96					C.S.			
ARDMORE (Avondale to Cleve. Ht)	A/C	4	2	94,97,00	93,96,00					Replace		
ARGONNE (ARDMORE TO MAYFIELD)	A/C	4	2	94,99,00	93,96,00						Yes	
AVONDALE (ADRIAN TO ELMWOOD)	A/C	4	2	94,00								
BAYARD (MAYWOOD TO OAKMOUNT)	A/A	4	3	94,00	93, 97	82						
BELVOIR MEWS	C	4	2	95					C.S.			
BLUESTONE (BELVOIR TO GREEN)	A/C	4	1	96	93, 96							
BLUESTONE (CITY LIMIT TO BELVOIR)	A/C	4	1/2									
BRADFORD	C	4	2	93, 99								
BUXTON	A/C	4	3	94, 99	95, 99							
CARLONE PLACE	C	4	2	93, 99					Minor jnt. Repair			
CLINTON	C	4	1	95,01		2004						
DARYL	C	4	1	95								
DILL	A/C	4	2	95	2004							
E. ANTISDALE (WRNSVILLE TO FENWICK)	A/C	4	4									
FAIROAKS	C	4	1	95		99			T.C.R.			
GLENRIDGE (CONCRETE SECTION)	C	4	1									
<b>HILLROCK</b>	C	4	2	93,99,00				2007	ht Repair by SE Service			
HOLMDEN	A/C	4	3	00	2004							

STREET	TYPE	RATING	WARD	CRACK SEAL	SEAL COAT	RECONST. YEAR	RESURF. YEAR	Minor Repairs	COMMENTS	CWD Recommendation	Flood Control Project Area	DEO Identified Priority
LOWER DONWELL	A/A	4	3	95	93, 95, 99	82						
LUCILLE (4380 TO GREEN)	A/C	4	2	95	93,01				S.C.			
MCFARLAND, K.G. to Trebisky	C	4	1	93, 99					C.S.			
MONARCH (ELMWOOD TO ADRIAN)	C	4	2	93, 96								
NEVILLE (WRENFORD TO BELVOIR)	A/C	4	3	94,00								
OKALONA	A/C	4	4	94, 99	2004				S.C.			
PARKSIDE	A/S	4	1		2004					Replace		
PLAINFIELD (1105 TO ARDMORE)	A/C	4	2	94,00	2004							
PLAINFIELD (BLUESTONE TO 1105)	C	4	2	94, 97					CURBS REPAIRED 2003			
QUEEN ANN COURT	C	4	1	93, 96		2005						
<b>QUEEN MARY</b>	C	4	1	93, 99				2007	ht Repair by SE Service			
QUILLIAMS	A/C	4	1	97	2004							
<b>RUSHTON (ST. GREGORY'S TO OAKMOUN</b>	A/S	4	3	94,98,00	93,96,00	00				Replace		
TEMBLETT TERRACE	A/A	4	4	95, 99	93, 95, 99	85						
TREBISKY	C	4	1			93				Replace		
UPPER DONWELL	A/A	4	3	95,01	95, 99	85			T.C.R.			
URBAN	A/C	4	1							Replace		
VERONA (WARRENSVILLE TO MIRAMAR)	A/C	4	4		00				C.S.			DEO
VILLA	A/C	4	2	95	93, 97							
WINSTON (ADRIAN TO ARDMORE)	A/C	4	1/2		93,96,01				S.C.		Yes	
WINSTON (GRANTLEIGH TO MAYFIELD)	A/C	4	2	94, 99	93,96,01				S.C.			
WRENFORD (BAYARD TO CEDAR)	A/C	4	4									
WYNCOTE	A/C	4	4	96	95, 99							
ACACIA	A/C	5	4	95	93, 96	03						
<b>ADRIAN (BELVOIR TO HOMESTEAD)</b>	A/C	5	1/2	94, 96	93, 97	2006						
ANDERSON (GREEN TO PROFESSOR)	C	5	1			91						
ARDENDALE	A/C	5	3	95,00	96,00	03						
<b>ARDMORE (BELVOIR EAST)</b>	A/C	5	2	94,99,00	96,00		2004			Replace	Yes	
<b>ARDMORE (BELVOIR WEST to Avondale )</b>	A/C	5	2	94,97,00	93,96,00		2004			Replace		
<b>ARGONNE (BLUESTONE TO Adrian)</b>	A/C	5	1/2	94, 96		2005			T.C.R.			
<b>AVONDALE (BLUESTONE TO ADRIAN)</b>	A/C	5	1		93, 96	2005			S.C.			
<b>AVONDALE (ELMWOOD TO MAYFIELD)</b>	A/C	5	2	94, 97	97		2006				Yes	
BAYARD (SCHOOL TO MAYWOOD)	A/S	5	3	94			2007					
BAYARD (WARRENSVILLE TO WRENFORD)	A/C	5	3	93, 94, 99	93, 97		02		C.S.			
BAYARD (WRENFORD TO BELVOIR)	A/C	5	3	94, 99			02					
BELWOOD	C	5	3			95						

STREET	TYPE	RATING	WARD	CRACK SEAL	SEAL COAT	RECONST. YEAR	RESURF. YEAR	Minor Repairs	COMMENTS	CWD Recommendation	Flood Control Project Area	DEO Identified Priority
BEXLEY	C	5	3			02						
<b>BROOKLINE</b>	A/C	<b>5</b>	2	95		<b>2007</b>						
BURGER	A/C	5	2			93						
CHARLTON	A/C	5	3	94		02				Replace		
CHELSTON	C	5	1	96		99						
CLIFFORD	C	5	2				2004					
COLONY (WEST OF WARRENSVILLE)	A/C	5	4	94, 96	95, 99	03				Replace		
CORWIN	A/C	5	3	97	95, 98	02						
COTTAGE	A/C	5	3	00	96,00	03						
<b>COVINGTON</b>	A/C	<b>5</b>	1	95		<b>2007</b>			Curbs good			
DENNIS CIRCLE	C	5	2	94, 97		01						
DENNIS CIRCLE (CUL-DE-SAC)	C	5	2									
DORSH (1152 TO MAYFIELD)	A/C	5	2	94, 96	97		02					
DORSH (CUL-DE-SAC TO 1152)	A/C	5	2	94, 96	97		02					
DORSHWOOD	C	5	2			96						
<b>E. ANTISDALE (WEST OF FENWICK)</b>	<b>A/C</b>	<b>5</b>	4			<b>2007</b>			in process			
E. GREEN	C	5	2			96						
EDMOND	C	5	2			95				Replace		
ELLISON (EAST OF MIRAMAR)	A/C	5	3	93, 97	95, 98	03						
ELLISON (WEST OF MIRAMAR)	C	5	3	93, 97	95, 99	03						
<b>ELMWOOD (WINSTON TO BELVOIR)</b>	A/C	<b>5</b>	2	94, 99	93,95,96,00	<b>2005</b>						
FARNHURST (S. LYN CIRCLE TO DORSH)	C	5	2	94, 99		00						
FELTON	C	5	3			99						
FENWICK	A/C	5	4		96		02					
GARDEN	C	5	3	95		96						
<b>GLENRIDGE (ASPHALT SECTION)</b>	A/A	<b>5</b>	1		97		<b>2006</b>					
GREENVALE (379 TO PRINCETON)	A/C	5	1	96	97		03		C.S.			
GREENVALE (LANCASTER TO 379)	A/C	5	1	96			03					
GREENWAY	C	5	4				95					
<b>GROSVENOR (WEST OF FENWICK)</b>	<b>A</b>	<b>5</b>	4	97	96		<b>2007</b>		in process			
<b>HALSEY</b>	<b>A</b>	<b>5</b>	4	95,01	97	<b>2006</b>			in process			
<b>HEROLD</b>	A/C	<b>5</b>	3	95			<b>2006</b>		New curbs, aprons			
KING GEORGE	C	5	1	93, 96			2005		Joint Repairs			
LAMBERT (4175 TO WRENFORD)	A/C	5	3	95		96						
LAMBERT (BEXLEY TO MIRAMAR)	C	5	3		95, 99	02						
LAMBERT (MIRAMAR TO 4175)	C	5	3	95		02						

STREET	TYPE	RATING	WARD	CRACK SEAL	SEAL COAT	RECONST. YEAR	RESURF. YEAR	Minor Repairs	COMMENTS	CWD Recommendation	Flood Control Project Area	DEO Identified Priority
LANGERDALE	A/C	5	4	95			02		C.S.			
LAUREL HILL	A/C	5	4				02					
LAWNWAY	C	5	3	95								
<b>LIBERTY</b>	A/C	<b>5</b>	2	93, 97	93, 95, 98	<b>2007</b>			Curbs good			
LILAC	A/C	5	2	95		03						
LINNELL	A/C	5	3	95		03						
LUCILLE (HOMESTEAD TO MONARCH)	C	5	2	96		01						
MAYDOR LANE	C	5	2	95		02						
<b>MIRAMAR (CEDAR TO VERONA)</b>	A/C	<b>5</b>	4	95	97		<b>2006</b>		New curbs, aprons			
MIRAMAR (FELTON TO BEXLEY)	A/C	5	3	95		03						
NEWBERRY	C	5	1	94		91						
NORMA	A/C	5	2	94		93						
PLAINFIELD (ARDMORE TO MAYFIELD)	A/C	5	2	94			03				Yes	
<b>PLYMOUTH</b>	A/C	<b>5</b>	1	95	97		<b>2006</b>		New curbs, aprons			
PRASSE	A/C	5	2	95, 99			03			Replace		
PRINCETON (BELVOIR EAST)	A/C	5	1	95	97		03					
PRINCETON (CAMBRIDGE TO BELVOIR)	A/C	5	1	95	97		02					
PRINCETON (QUILLIAMS TO CAMBRIDGE)	A/C	5	1	95			02					
PROFESSOR (ANDERSON TO RIDGEBURY)	A/C	5	1/2	97	95, 98	03 (Curbs)						
PROFESSOR (EDENWOOD TO BURGER)	A/C	5	2	97	95, 98	03 (Curbs)						
PROFESSOR (EDSAL TO FARNHURST)	A/C	5	2	99		02						
SALISBURY	A/C	5	1	95			03					
SHEFFIELD (ARDMORE TO MAYFIELD)	C	5	2	95		99						
SOUTH LYN CIRCLE (NORTH)	C	5	2	95, 98		00						
STONEHAVEN	A/C	5	3/4	94, 99	97	03				Replace		
<b>SUFFOLK</b>	A/C	<b>5</b>	1	95		<b>2007</b>			T.C.R.			
SWAFFIELD	C	5	2	93, 97		01						
<b>TELHURST (CONCRETE)</b>	<b>C</b>	<b>5</b>	2	95			<b>2007</b>					
TELHURST TO CONCRETE	A/C	5	2	95, 98	97		03					
VERONA (WRENFORD TO BELVOIR)	A/A	5	4		95,00	82	02					
VICTORY	C	5	2	94, 97	97	01				Replace		
WALLINGFORD	C	5	1	95		99				Replace		
WANDSWORTH	A/C	5	3			95						
<b>WARRENDALE</b>	<b>A</b>	<b>5</b>	4	96		<b>2006/2007</b>						
<b>WAVERLY</b>	A/C	<b>5</b>	1	95		<b>2007</b>						
WHITEHALL, Bridge to Dorsh	C	5	2	93,99,00			2005		Joint Repair			

STREET	TYPE	RATING	WARD	CRACK SEAL	SEAL COAT	RECONST. YEAR	RESURF. YEAR	Minor Repairs	COMMENTS	CWD Recommendation	Flood Control Project Area	DEO Identified Priority
WHITEHALL, Green to Bridge	C	5	2	93,99,00		2004						
<b>WINSTON (BLUESTONE TO ADRIAN)</b>	A/A	5	2		93,96,01	<b>2006</b>						
WRENFORD (BELVOIR TO NEVILLE)	C	5	3	96		02						
WRENFORD (NEVILLE TO BAYARD)	C	5	3	96		93						

**DENOTES CHANGED STATUS THIS YEAR**

DOPWIC RATING CODE:

- EXCELLENT = 5
- GOOD = 4
- FAIR = 3
- POOR = 2
- CRITICAL = 1

ABBREVIATIONS:

- A/A: ASPHALT OVERLAY ON ASPHALT BASE
- A/C: ASPHALTOVERLAY ON CONCRETE BASE
- C: CONCRETE
- C.S.: CRACK SEAL
- S.C.: SEAL COAT
- T.C.R.: TOTAL CURB REPLACEMENT